

Thermography Inspection



Inspected Time: 2010-02-17 8:29 AM Inspected Location:																	
File Name	IMAGE6.IRI	Created Date	Mittwoch, 17. Februar 2010	Created Time	08:08:41												
Emissivity	0.91	Humidity	60%	Distance	3.1m												
Ambient	8.4°C	Max Temp	-13.2°C	Min Temp	-16.0°C												
IR Image				<table border="1"> <thead> <tr> <th>Objekt</th> <th>Wert</th> </tr> </thead> <tbody> <tr> <td>Parameter</td> <td></td> </tr> <tr> <td>Max</td> <td>-13.2°C</td> </tr> <tr> <td>L1:MittelTemp</td> <td>-14.3°C</td> </tr> <tr> <td>L1:MaxTemp</td> <td>-13.2°C</td> </tr> <tr> <td>L1:MinTemp</td> <td>-15.8°C</td> </tr> </tbody> </table>		Objekt	Wert	Parameter		Max	-13.2°C	L1:MittelTemp	-14.3°C	L1:MaxTemp	-13.2°C	L1:MinTemp	-15.8°C
Objekt	Wert																
Parameter																	
Max	-13.2°C																
L1:MittelTemp	-14.3°C																
L1:MaxTemp	-13.2°C																
L1:MinTemp	-15.8°C																
Visible Image																	
Profile																	